

Public Works Department 4444 Walbert Avenue Allentown, PA 18104-1699

Phone: 610-398-0407 Fax: 610-398-6898

# Facsimile Transmission Sheet

Date:

11/29/11

To:

Shenna Ripple, DEP

Fax Number 610-861-2072

From:

Thomas R. Uff, Superintendent, Underground

**Utilities & Traffic** 

Subject:

**SSO Report to DEP** 

Number of pages including this transmission sheet: 4

#### <u>Message:</u>


The attached SSO report is the result of an overflow at Township Authority Manhole MH-1. See attached map. This happened Wednesday, November 23, 2011. Note: As stated before; We have performed extensive repairs and sealing of manholes in this area over the past year. The combined Townships, County, and City flow, was unable to enter the City main and the backpressure caused the casting to lift,

WATER QUALITY
COUNTY: Lehigh

NOV 2 9 2011 SP

MUNIC: S. Whitehell
FAGHETY:
FILE CODE: General SEWAGE

Thomas R. Uff



## Sanitary Sewer Overflow (SSO) Report to PADEP

2. Your organization name and address?  3. Date found and specific location of SSO?  4. How was SSO discovered?  By who?  5. Start and end time of SSO?  6. Date, time and name of person who notified PADEP of SSO?  7. Description and actual or estimated volume of SSO  (land, roadway, basement, swale, storm sewer, creek, etc)  8. Where, precisely, did SSO go? (land, roadway, basement, swale, storm sewer, creek, etc)  8. What caused SSO? How was it stopped?  10. Describe extent of contamination and how it was desined up  11. What actions will be taken to prevent a re-occurrence?  12. Your organization name and surface of prevent a re-occurrence?  13. Date found and specific location of SSO (actual or estimated)  14. How was sSO discovered?  15. Start and end time of SSO (actual or estimate of person who notified PADEP of SSO?  16. Date, time and name of person who notified PADEP of SSO?  17. Description and actual or estimated volume of SSO  18. Where, precisely, did SSO go? (land, roadway, basement, swale, storm sewer, creek, etc)  19. What caused SSO? How was it stopped?  10. Describe extent of contamination and how it was desined up  10. Describe extent of contamination and how it was desined up  11. What actions will be taken to prevent a re-occurrence?  12. What actions will be taken to prevent a re-occurrence?  13. Are a page as SPAY shower and support a support of spaying and the prevent as re-occurrence?  14. PROVINCE PADEP AND STARE SPAY SPAYING WILL SE LETTED AND SPAYING WILL SE LETTED								
2. Your organization name and address?  3. Date found and specific location of SSO?  4. How was SSO discovered?  By who?  5. Start and end time of SSO (actual or estimate?)  6. Date, time and name of parson who notified PADEP of SSO?  7. Description and actual or estimated volume of SSO  8. Where, precisely, did SSO go? (land, roadway, basement, swale, storm sewer, creek, etc)  8. What caused SSO?  9. What caused SSO?  10. Describe extent of contemination and how it was cleaned up  11. What actions will be taken to prevent a re-occurrence?  11. What actions will be taken to prevent a re-occurrence?  12. Your organization name and advance of prevent a re-occurrence?  13. Date found and specific location of SSO?  14. Another in the found and specific location of SSO (actual or estimated)  15. Start and end time of SSO  16. Date, time and name of parson who notified PADEP of SSO?  16. Date, time and name of parson who notified PADEP of SSO?  17. Description and actual or estimated volume of SSO  18. Where, precisely, did SSO go?  19. What caused SSO?  19. What caus		Date: 11/2+/n Name: 1746m#5 CLFF Signature: 1,111 Phone #: 6/0 - 398 - 04017						
3. Date found and specific location of SSO?  4. How was SSO discovered?  By who?  5. Start and end time of SSO (actuel or estimate?)  6. Date, time and name of person who notified PADEP of SSO?  7. Description and actual or estimated volume of SSO  8. Where, precisely, did SSO go? (land, roadway, basement, swale, storm sewer, creek, etc)  9. What caused SSO?  How was it stopped?  8. Where, precisely, did SSO go?  (land, roadway, basement, swale, storm sewer, creek, etc)  9. What caused SSO?  How was it stopped?  10. Describe extent of contamination and how it was cleaned up  11. What actions will be taken to prevent a re-occurrence?  When?  11. What actions will be taken to prevent a re-occurrence?  When?	_	SOUTH WASTERFALL TUP BUTHORITY						
4. How was \$50 discovered?  By who?  5. Start and end time of \$50 (actual or estimate?)  6. Date, time and name of parson who notified PADEP of \$50?  7. Description and actual or estimated volume of \$50  8. Where, precisely, did \$50 go? (land, roadway, basement, swale, storm sewer, creek, etc)  9. What caused \$50?  How was it stopped?  10. Describe extent of contamination and how it was cleaned up  11. What actions will be taken to prevent a re-occurrence?  When?  11. What actions will be taken to prevent a re-occurrence?  When?  12. What actions will be taken to prevent a re-occurrence?  When?		11/23/11. MANAGE MAY LOCATED IN A CEMPOR ALLENTOWN PARK NEAR THE INTERSECTIONS OF						
6. Date, time and name of person who notified PADEP of SSO?  Time: 1930 MR5 - NDICE MATL.  Name: THOMAS UFF  7. Description and actual or estimated volume of SSO  8. Where, precisely, did SSO go? (land, roadway, basement, swale, storm sewer, creek, etc)  9. What caused SSO? How was it stopped?  9. What caused SSO? How was it stopped?  10. Describe extent of contamination and how it was cleaned up  11. What actions will be taken to prevent a re-occurrence? When?  12. What actions will be taken to prevent a re-occurrence? When?  13. What actions will be taken to prevent a re-occurrence? When?		OF CINY EMPLOYEES AND AUTHORING INPLOYEES						
7. Description and actual or estimated volume of SSO  8. Where, precisely, did SSO go? (land, roadway, basement, swale, storm sewer, creek, etc)  9. What caused SSO? How the stopped?  10. Describe extent of contamination and how it was cleaned up  11. What actions will be taken to prevent a re-occurrence?  When?  12. When?  13. When?  14. What actions will be taken to prevent a re-occurrence?  When?		WE ONES TRY 1/23/11						
7. Description and actual or estimated volume of SSO  8. Where, precisely, did SSO go? (land, roadway, basement, swale, storm sewer, creek, etc)  9. What caused SSO? How was it stopped?  10. Describe extent of contamination and how it was cleaned up  11. What actions will be taken to prevent a re-occurrence?  When?  12. When Precisely, did SSO go? (land, roadway, basement, swale, storm sewer, creek, etc)  13. What caused SSO? How was it stopped?  14. What caused SSO? How was it stopped?  15. What caused SSO? How was it stopped?  16. Describe extent of contamination and how it was cleaned up  17. What actions will be taken to prevent a re-occurrence?  18. When?  19. What caused SSO? How was it stopped?  10. Describe extent of contamination and how it was cleaned up  10. Describe extent of contamination and how it was cleaned up  11. What actions will be taken to prevent a re-occurrence?  12. What actions will be taken to prevent a re-occurrence?  13. What actions will be taken to prevent a re-occurrence?  14. What actions will be taken to prevent a re-occurrence?  15. When?	6. Date, time and name of person who notified PADEP of SSO ?	Date: 11/29/11 Time: 1430 ARS - VOICE MAIL. Name: THOMAS UFF						
8. Where, precisely, did SSO go? (land, roadway, basement, swale, storm sewer, creek, etc)  9. What caused SSO? How was it stopped?  10. Describe extent of contamination and how it was cleaned up  11. What actions will be taken to prevent a re-occurrence? When?  12. What caused SSO?  ### PLOUT FLOW FROM BUTTER PLOT FROM BUTTER PLOT WINT  #### PROPERTY OF ALLENDOWN PLANT  ###################################		WORKNOWN VOLUME OF SENETHERY SENTER FLOWS -FLOW APPEARED TO BE MENOR-						
9. What caused SSO? How was it stopped?  ###################################	(land, roadway, basement, swale,	SEO WENT TO LETTLE LEATEN CHEEK						
contamination and how if was cleaned up  BACK FAMOUNT FOR STAND BUT ARETH.  11. What actions will be taken to prevent a re-occurrence? When?  When?		MAIN TO ENTER PLACE CONNECTOR TO						
11. What actions will be taken to prevent a re-occurrence? When?  THE MANNEY (ASTENG WILL BE LITTED AND SERVED. THES WILL BE LITTED AND SERVED. THES WILL BE PERFORMED.  AFTER PROPERTY TO DAY ENOUGH TO SAYOUR.	contamination and how it was	BACK FAND PEPE, THE PROPERTY WELL BE						
TANKANTINIA ENGATE BARANTA (MENTALA MARIA	prevent a re-occurrence ? When ?	THE MANUALA CASTENG WELL BE LIXTED AND SEAL REPLACED. THIS WILL BE PERFORMED AFTER FROM TO DAY ENOUGH TO SAPORT						
CASTENS.	7/14	CASTENS.						

## Sanitary Sewer Overflow (SSO) Report to PADEP

THE PREA MARKED ON AMPLHED NAD

12. Other comments?

#### Musinski, Patrick

From:

PW Uff Thomas R. <ufft@southwhitehalltwp.org>

Sent:

Wednesday, September 07, 2011 11:49 AM

To:

Kennedy, Robert; Joseph McMahon; Kerchusky, Robert

Cc:

Young, Richard; PW Balliet James; rickklotz@aol.com; scott@imperial-excavating.com; Aurel

Arndt; Alan Hill; Kevin German; Tom Williams; shenning@pidcockcompany.com; Dennis E.

Harman; Phillips, Michael; Malloy, David; Musinski, Patrick; EX Hammer Jon A.

Subject:

RE: South Whitehall SSO

At this time: The area in the park surrounding the vault is still flooded with water flowing several feet deep. We will obviously have to wait for the creek to recede before evaluating the damage and entry possibilities. We will move in as soon as it is safe to do so.

No matter what we do here, it does not solve the problem of putting waste water from several municipalities (including West End City sewer customers, Salisbury Twp. customers, LCA customers, etc.) into one City pipe already normally flowing close to full. The vault lid that moved off its foundation weighs several thousand pounds. The SWT hydraulic flow alone did not move it. All flows combined overwhelmed the downstream pipe capability and caused the hydraulic surge that moved it. This indicates a regional problem, not only an SWTA problem. It happens to be an SWTA manhole that is serving as the "relief valve".

We will take care of our end ASAP and need your help to take care of yours.

Joe M. and Bob K.: Thanks for the offer of the ground pad plates; we will contact you if we can use them.

Thomas R. Uff, CUSA
Utility and Traffic Superintendent
South Whitehall Twp.
ufft@southwhitehall.com
610-398-0407

-----Original Message-----

From: Kennedy, Robert [mailto:Kennedy@allentowncity.org]

Sent: Wednesday, September 07, 2011 10:10 AM

To: Joseph McMahon; PW Uff Thomas R.; Kerchusky, Robert

Cc: Young, Richard; PW Balliet James; rickklotz@aol.com; scott@imperial-excavating.com; Aurel Arndt; Alan Hill;

Kevin German; Tom Williams

Subject: RE: South Whitehall SSO

I totally agree. The sooner it's fixed the better. I believe that it poses a significant hazard to the WFP and severely impacts drinking water production for the city. Given the severity of the past storms we don't need any extra limitations on drinking water production.

From: Joseph McMahon [mailto:josephmcmahon@lehighcountyauthority.org]

Sent: Wednesday, September 07, 2011 9:55 AM

To: Kennedy, Robert; PW Uff Thomas R.; Kerchusky, Robert

Cc: Young, Richard; PW Balliet James; rickklotz@aol.com; scott@imperial-excavating.com; Aurel Arndt; Alan Hill;

Kevin German; Tom Williams

Subject: RE: South Whitehall SSO

Tom,

Considering the severity of the overflow which means that the City can't use the Little Lehigh for water supply which will include the increased cost of pumping and treating Lehigh water and LCA's increased expenses at Park Pump Station due to the SWT leaking manhole you may be able to use heavy steel plates or boards to drive the heavy equipment over in order to get to the manhole fixed as soon as possible so that we don't have to wait a

week or more before the area dries out to fix the manhole. We have 2 steel plate and 8 heavy plastic plates you can borrow for this job. The City may be willing to lend you steel plates and Imperial may also have plates.

Regards,

Joe

Joseph M. McMahon III Operations Manager Lehigh County Authority

From: Kennedy, Robert [mailto:Kennedy@allentowncity.org]

Sent: Wednesday, September 07, 2011 9:25 AM

To: PW Uff Thomas R.; Kerchusky, Robert

Cc: Young, Richard; PW Balliet James; rickklotz@aol.com; Joseph McMahon; scott@imperial-excavating.com

Subject: RE: South Whitehall SSO

Thanks!!

From: PW Uff Thomas R. [mailto:ufft@southwhitehalltwp.orq]

Sent: Wednesday, September 07, 2011 8:55 AM

To: Kennedy, Robert; Kerchusky, Robert

Cc: Young, Richard; PW Balliet James; rickklotz@aol.com; Joseph McMahon; scott@imperial-excavating.com

Subject: RE: South Whitehall SSO

#### Good Morning:

The lid was placed back on the vault sometime between Thursday 9/1 and Friday 9/2. Steel straps were ordered from Monarch Precast to secure the lid to the vault like was done with the others in the area. They did not arrive yet. As soon as the straps arrive they will be installed.

I was out of town from 9/1 until this morning, so I just now see your pictures that show the vault lid moved off the vault again. We will get the lid back on ASAP, but have to allow the area time to dry out so it can support the weight of the machine required to lift the lid.

Thomas R. Uff, CUSA
Utility and Traffic Superintendent
South Whitehall Twp.
ufft@southwhitehall.com
610-398-0407

----Original Message----

From: Kennedy, Robert [mailto:Kennedy@allentowncity.org]

**Sent:** Tuesday, September 06, 2011 5:24 PM **To:** Kerchusky, Robert; PW Uff Thomas R.

Cc: Young, Richard; PW Balliet James; PW Weber James H.

Subject: RE: South Whitehall SSO

Tom, The manhole above Shriver's bridge that had been fixed with a new casting is leaking badly again. The casting has been pushed up and a lot of sewage is pushing out and running into Little Lehigh making it impossible to run the water Filtration Plant. We were up at 5 PM on 9-6-11 and it was leaking severely.

#### Musinski, Patrick

From:

PW Uff Thomas R. <ufft@southwhitehalltwp.org>

Sent:

Wednesday, September 07, 2011 11:49 AM

To:

Kennedy, Robert; Joseph McMahon; Kerchusky, Robert

Cc:

Young, Richard; PW Balliet James; rickklotz@aol.com; scott@imperial-excavating.com; Aurel Arndt; Alan Hill; Kevin German; Tom Williams; shenning@pidcockcompany.com; Dennis E.

Harman; Phillips, Michael; Malloy, David; Musinski, Patrick; EX Hammer Jon A.

Subject:

RE: South Whitehall SSO

At this time: The area in the park surrounding the vault is still flooded with water flowing several feet deep. We will obviously have to wait for the creek to recede before evaluating the damage and entry possibilities. We will move in as soon as it is safe to do so.

No matter what we do here, it does not solve the problem of putting waste water from several municipalities (including West End City sewer customers, Salisbury Twp. customers, LCA customers, etc.) into one City pipe already normally flowing close to full. The vault lid that moved off its foundation weighs several thousand pounds. The SWT hydraulic flow alone did not move it. All flows combined overwhelmed the downstream pipe capability and caused the hydraulic surge that moved it. This indicates a regional problem, not only an SWTA problem. It happens to be an SWTA manhole that is serving as the "relief valve".

We will take care of our end ASAP and need your help to take care of yours.

Joe M. and Bob K.: Thanks for the offer of the ground pad plates; we will contact you if we can use them.

Thomas R. Uff, CUSA
Utility and Traffic Superintendent
South Whitehall Twp.
ufft@southwhitehall.com
610-398-0407

----Original Message----

From: Kennedy, Robert [mailto:Kennedy@allentowncity.org]

Sent: Wednesday, September 07, 2011 10:10 AM

To: Joseph McMahon; PW Uff Thomas R.; Kerchusky, Robert

Cc: Young, Richard; PW Balliet James; rickklotz@aol.com; scott@imperial-excavating.com; Aurel Arndt; Alan Hill;

Kevin German; Tom Williams

Subject: RE: South Whitehall SSO

I totally agree. The sooner it's fixed the better. I believe that it poses a significant hazard to the WFP and severely impacts drinking water production for the city. Given the severity of the past storms we don't need any extra limitations on drinking water production.

From: Joseph McMahon [mailto:josephmcmahon@lehighcountyauthority.org]

Sent: Wednesday, September 07, 2011 9:55 AM

To: Kennedy, Robert; PW Uff Thomas R.; Kerchusky, Robert

Cc: Young, Richard; PW Balliet James; rickklotz@aol.com; scott@imperial-excavating.com; Aurel Arndt; Alan Hill;

Kevin German; Tom Williams

Subject: RE: South Whitehall SSO

Tom,

Considering the severity of the overflow which means that the City can't use the Little Lehigh for water supply which will include the increased cost of pumping and treating Lehigh water and LCA's increased expenses at Park Pump Station due to the SWT leaking manhole you may be able to use heavy steel plates or boards to drive the heavy equipment over in order to get to the manhole fixed as soon as possible so that we don't have to wait a

week or more before the area dries out to fix the manhole. We have 2 steel plate and 8 heavy plastic plates you can borrow for this job. The City may be willing to lend you steel plates and Imperial may also have plates.

Regards,

Joe

Joseph M. McMahon III Operations Manager Lehigh County Authority

From: Kennedy, Robert [mailto:Kennedy@allentowncity.org]

Sent: Wednesday, September 07, 2011 9:25 AM

To: PW Uff Thomas R.; Kerchusky, Robert

Cc: Young, Richard; PW Balliet James; rickklotz@aol.com; Joseph McMahon; scott@imperial-excavating.com

Subject: RE: South Whitehall SSO

Thanks!!

From: PW Uff Thomas R. [mailto:ufft@southwhitehalltwp.org]

Sent: Wednesday, September 07, 2011 8:55 AM

To: Kennedy, Robert; Kerchusky, Robert

Cc: Young, Richard; PW Balliet James; rickklotz@aol.com; Joseph McMahon; scott@imperial-excavating.com

Subject: RE: South Whitehall SSO

#### Good Morning:

The lid was placed back on the vault sometime between Thursday 9/1 and Friday 9/2. Steel straps were ordered from Monarch Precast to secure the lid to the vault like was done with the others in the area. They did not arrive yet. As soon as the straps arrive they will be installed.

I was out of town from 9/1 until this morning, so I just now see your pictures that show the vault lid moved off the vault again. We will get the lid back on ASAP, but have to allow the area time to dry out so it can support the weight of the machine required to lift the lid.

Thomas R. Uff, CUSA
Utility and Traffic Superintendent
South Whitehall Twp.
ufft@southwhitehall.com
610-398-0407

----Original Message----

From: Kennedy, Robert [mailto:Kennedy@allentowncity.org]

**Sent:** Tuesday, September 06, 2011 5:24 PM **To:** Kerchusky, Robert; PW Uff Thomas R.

Cc: Young, Richard; PW Balliet James; PW Weber James H.

Subject: RE: South Whitehall SSO

Tom, The manhole above Shriver's bridge that had been fixed with a new casting is leaking badly again. The casting has been pushed up and a lot of sewage is pushing out and running into Little Lehigh making it impossible to run the water Filtration Plant. We were up at 5 PM on 9-6-11 and it was leaking severely.

#### Musinski, Patrick

From:

PW Uff Thomas R. <ufft@southwhitehalltwp.org>

Sent:

Wednesday, September 07, 2011 11:49 AM

To:

Kennedy, Robert; Joseph McMahon; Kerchusky, Robert

Cc:

Young, Richard; PW Balliet James; rickklotz@aol.com; scott@imperial-excayating.com; Aurel Arndt; Alan Hill; Kevin German; Tom Williams; shenning@pidcockcompany.com; Dennis E.

Harman; Phillips, Michael; Malloy, David; Musinski, Patrick; EX Hammer Jon A.

Subject:

RE: South Whitehall SSO

At this time: The area in the park surrounding the vault is still flooded with water flowing several feet deep. We will obviously have to wait for the creek to recede before evaluating the damage and entry possibilities. We will move in as soon as it is safe to do so.

No matter what we do here, it does not solve the problem of putting waste water from several municipalities (including West End City sewer customers, Salisbury Twp. customers, LCA customers, etc.) into one City pipe already normally flowing close to full. The vault lid that moved off its foundation weighs several thousand pounds. The SWT hydraulic flow alone did not move it. All flows combined overwhelmed the downstream pipe capability and caused the hydraulic surge that moved it. This indicates a regional problem, not only an SWTA problem. It happens to be an SWTA manhole that is serving as the "relief valve".

We will take care of our end ASAP and need your help to take care of yours.

Joe M. and Bob K.: Thanks for the offer of the ground pad plates; we will contact you if we can use them.

Thomas R. Uff. CUSA Utility and Traffic Superintendent South Whitehall Twp. ufft@southwhitehall.com 610-398-0407

----Original Message----

From: Kennedy, Robert [mailto:Kennedy@allentowncity.org]

Sent: Wednesday, September 07, 2011 10:10 AM

To: Joseph McMahon; PW Uff Thomas R.; Kerchusky, Robert

Cc: Young, Richard; PW Balliet James; rickklotz@aol.com; scott@imperial-excavating.com; Aurel Arndt; Alan Hill;

Kevin German; Tom Williams Subject: RE: South Whitehall SSO

I totally agree. The sooner it's fixed the better. I believe that it poses a significant hazard to the WFP and severely impacts drinking water production for the city. Given the severity of the past storms we don't need any extra limitations on drinking water production.

From: Joseph McMahon [mailto:josephmcmahon@lehighcountyauthority.org]

Sent: Wednesday, September 07, 2011 9:55 AM

To: Kennedy, Robert; PW Uff Thomas R.; Kerchusky, Robert

Cc: Young, Richard; PW Balliet James; rickklotz@aol.com; scott@imperial-excavating.com; Aurel Arndt; Alan Hill;

Kevin German; Tom Williams

Subject: RE: South Whitehall SSO

Tom,

Considering the severity of the overflow which means that the City can't use the Little Lehigh for water supply which will include the increased cost of pumping and treating Lehigh water and LCA's increased expenses at Park Pump Station due to the SWT leaking manhole you may be able to use heavy steel plates or boards to drive the heavy equipment over in order to get to the manhole fixed as soon as possible so that we don't have to wait a

week or more before the area dries out to fix the manhole. We have 2 steel plate and 8 heavy plastic plates you can borrow for this job. The City may be willing to lend you steel plates and Imperial may also have plates.

Regards,

Joe

Joseph M. McMahon III Operations Manager Lehigh County Authority

From: Kennedy, Robert [mailto:Kennedy@allentowncity.org]

Sent: Wednesday, September 07, 2011 9:25 AM

To: PW Uff Thomas R.; Kerchusky, Robert

Cc: Young, Richard; PW Balliet James; rickklotz@aol.com; Joseph McMahon; scott@imperial-excavating.com

Subject: RE: South Whitehall SSO

Thanks!!

From: PW Uff Thomas R. [mailto:ufft@southwhitehalltwp.orq]

Sent: Wednesday, September 07, 2011 8:55 AM

To: Kennedy, Robert; Kerchusky, Robert

Cc: Young, Richard; PW Balliet James; rickklotz@aol.com; Joseph McMahon; scott@imperial-excavating.com

Subject: RE: South Whitehall SSO

#### Good Morning:

The lid was placed back on the vault sometime between Thursday 9/1 and Friday 9/2. Steel straps were ordered from Monarch Precast to secure the lid to the vault like was done with the others in the area. They did not arrive yet. As soon as the straps arrive they will be installed.

I was out of town from 9/1 until this morning, so I just now see your pictures that show the vault lid moved off the vault again. We will get the lid back on ASAP, but have to allow the area time to dry out so it can support the weight of the machine required to lift the lid.

Thomas R. Uff, CUSA
Utility and Traffic Superintendent
South Whitehall Twp.
ufft@southwhitehall.com
610-398-0407

-----Original Message-----

From: Kennedy, Robert [mailto:Kennedy@allentowncity.org]

**Sent:** Tuesday, September 06, 2011 5:24 PM **To:** Kerchusky, Robert; PW Uff Thomas R.

Cc: Young, Richard; PW Balliet James; PW Weber James H.

Subject: RE: South Whitehall SSO

Tom, The manhole above Shriver's bridge that had been fixed with a new casting is leaking badly again. The casting has been pushed up and a lot of sewage is pushing out and running into Little Lehigh making it impossible to run the water Filtration Plant. We were up at 5 PM on 9-6-11 and it was leaking severely.

# P. 002 Pfu Ce:DF

### Sanitary Sewer Overflow (SSO) Report to PADEP

Date, Name, Phone # of person completing this report	Date: 8/30/11 Name: ** ** ** ** ** ** ** ** ** ** ** ** **
Your organization name and address?	SOUTH LONETEPHELL TWO DUTHERETY HUMA LOTALBERT AUG RLLENTOWON) IN 18104
Date found and <u>specific</u> location of SSO ?	B/29/11. MANINGE MH-1 LOCATED IN A CETY OF ALLENTOWN PARK NAAR THE LITTERSEETEDING OF MARTEN LUTHER KING TR PREVER MIND LEHTCH PARKUSAN
4. How was SSO discovered? By who?	OF CENTER BY OBSERVATION ROTO ENST.  OF CENTER PROLONGES AND ANTHONORY DRYLOYERS  CHECKENS THE DREST.
Start and end time of SSO (actual or estimate?)	500000 3/20/11 TO PONDAY 8/29/11
6. Date, time and name of person who notified PADEP of SSO ?	Date: 8/30/11  Time: 0950 AM  Name: THOMAS UFF  Ch 94 / Gas Senage
Description and actual or estimated volume of SSO	WALKOUN VOLUME OF SPINITFY SERVER FROM
8. Where, <u>precisely</u> , did SSO go ? (land, roadway, basement, swale, storm sewer, creek, etc)	SSO WENT TO LETTLE LEMEBY CREEK
9. What caused SSO ? How was it stopped ?	BACKUP OF SEWER FLOW FIN (ITY SEWER MAIN) DED NOT ALLOWS FLOW FROM AUTHORSONY MAIN TO ENTER PITE (OUNTER TEON) TO CETY OF ALLOWOODN) PLANT
10. Describe extent of contamination and how it was cleaned up	SENSE PERRES REMILIONO EN THE AREA OF THE MANIMOLE AFTER FLOWS WENT BACK THO PEPE, THE OBSATS WAS REMOVED AND LINE STREAD OVER AREA.
11. What actions will be taken to prevent a re-occurrence? When?	THE MANNOLE LED WELL BOT RESEARCED AND REPRESENT OVER HARE. THE LED WILL BE BOLTED TO CASTENDS. TO BE DON'T AS SOUTH AS LEFTENDE FOUTE. CAN ENTER
	SOFT AREA AROUND VAULT,

Sanitary Sewer Overflow (SSO) Report to PADEP

JEE AREA MARKET ON ATTACKED MAPS

12. Other comments?



Public Works Department 4444 Walbert Avenue Allentown, PA 18104-1699 Phone: 610-398-0407

Fax: 610-398-6898

# Facsimile Transmission Sheet

Date:

08/30/11

To:

Patric Musinsky, Water Quality Supervisor,

**PADEP** 

Fax Number 570-830-3016

From:

Thomas R. Uff, Superintendent, Underground

**Utilities & Traffic** 

Subject:


SSO Report: Cedar Creek Interceptor Line


Number of pages including this transmission sheet: 6


#### Message:

The attached SSO report is the result of an overflow at a Township Authority Manhole. This happened Sunday 08/28/11 into Monday 08/29/11.

Note: We have performed extensive repairs and sealing of manholes in this area over the past year. The flow was unable to enter the City main and the backpressure caused the lid to lift.







MAR/15/2011/TUE 09:05 AM

# FILE: GENERAL Senaye Southirehall Lohigh Sanitary Sewer Overtion (SSU) Report to PADEP

P. 002 CC:SR CC:DF


	CC,DF
Date, Name, Phone # of person completing this report	Date: 3 /8 /2011 Name: 7 / 2011 Phone #: 610 - 398 - 0487 Signature: 7 / 14/6
Your organization name and address?	SOUTH WHITEHALL TWP. 4444 WALBERT ALE ALLENTOUN DA 19104
Date found and <u>specific</u> location of SSO ?	3/11/2011 JANITARY JENTER SIPHON CHAMBER ALLESS MANTOLES (MILLAMITA) ALONG MARTIN LUTHER KIN TR. BRIVE, ALLENTOWN AND MALLON,
4. How was SSO discovered? By who ?	TR. BRIVE, ALCENTOWN AND MAILA.  BY CITY OF ALLENTOWN EMPLOYEE AND TWA  IMPLOYEE.
Start and end time of SSO     (actual or estimate?)	on 3/11/2014 - AS NOTED BY TUP EXPLOYED
Who notified PADEP of SSO 2	Date: 3/15/2011 DAT NUSTROSKI - BY EMAIL Time: 0823 Name: THOMAS UFF
Description and actual or estimated volume of SSO	OUERFLOW OUT OF HATCHES OF SEPHON CHAMBERS, - UNKNOWN VOLUME, OWERFLOW FROM 1441-A GASKET SEAL - UNKNOWN VOLUME
8. Where, <u>precisely</u> , did SSO go ? (land, roadway, basement, swale, storm sewer, creek, etc)	150 WAS WASHED AWAY BY CREEK FLOWS
9. What caused SSO ? How was it stopped ?	JEALS EN NEW REPARES BLEW OUT DUE TO PRESSORE OF FLOW I OI POSSIBLE CAUSE OF WHICH OVER WHENED CLIPS SYSTEM AND BACKED UP FUTO TOWNSHIP MITTIN. STEPPED WHEN VOLUME IN CLIPS MAIN ALLOWED FORMSHIP FLOW. IN MINING
10. Describe extent of contamination and how it was cleaned up	CONKROWN EXTENT OF CONTAMINATION.  MINOR CLEAN UP WAS PERFORMED BELAUSE  THERE WAS PENDE DEBRIS ROTED AT TERE  OF INSPECTION. PREA WAS LETTE ALSO.
11. What actions will be taken to prevent a re-occurrence? When?	TOIONSHIP MAS AN ACTIVE ISI MUGRAM.  UNKNOWN WHAT CITY WELL DO TO CONTROL  FLOW SURGES IN THETER MAINS, TOWNSHIP  RELENTLY SEALED HANNELES IN THIS AREA.

12. Other comments?

DN FURTHER ENGINEEM MANAGES FOR THE CETTY

OF ALLENGTOWN WERE FULL ENDERFORD THAT

THE PLANT AS DESTUNDED.





Public Works Department 4444 Walbert Avenue Allentown, PA 18104-1699

Phone: 610-398-0407

Fax: 610-398-6898

## **Facsimile Transmission Sheet**

Date:

03/15/11

To:

Patric Musinski, DEP

Fax Number 570-830-3016

From:

Thomas R. Uff, Superintendent, Underground

**Utilities & Traffic** 

**Subject:** 

**SSO Report to DEP** 

Number of pages including this transmission sheet: 4

#### Message:

Please note that the SSOs occurred from both the siphon chamber lid gaskets, and at the gasket seal on manhole MH.1-A. These are located at the three points circled on the plan. We will repair these as soon as we can get equipment in to lift the structures to replace the gaskets.


Thomas R. Uff

## Sanitary Sewer Overflow (SSO) Report to PADEP S. wh means The

	handstatic bearing to the second
Date, Name, Phone # of person completing this report	Date - La Za
Your organization name and address?	SOUTH WHITEHALL TWP. 4444 WHEBERT AUS ALLENTOUN DA 18104
Date found and <u>specific</u> location of SSO ?	
4. How was SSO discovered? By who ?	TR. BRIVE, ALLENTOWN AND MAI-A.  BY CITY OF ALLENTOWN EMPLOYEE AND TWO  EMPLOYEE.
Start and end time of SSO     (actual or estimate?)	ON 3/7 /2011 - AS NOTED BY TWO EMPLOYETS
Date, time and name of person who notified PADEP of SSO ?	Date: 3/11/2011 DAY NUSTROSKI - VOLCE MAIL & MAIL TIME: 0824 Name: THOMAS UFF
7. Description and actual or estimated volume of SSO	OUBRAFIOUS OUT OF MATCHES OF SEPHON CHAMBERS LENKHOUDN VOLLENE, OUTRELOW FROM MHI-A GASKET SEARL - LENKNOWN VOLLENE
8. Where, precisely, did SSO go? (land, roadway, basement, swale, storm sewer, creek, etc)	550 WAS WASKED AWAY BY CREEK FLOW
9. What caused SSO ? How was it stopped ?	JEALS IN NOW REPORTS BLEW OUT OVE TO PRESSURE OF FLOWS  IS I POSSIBLE CAUSE OF WHICH OVERWHEND  CITY SYSTEM AND BACKED UP INTO TOWNSHIP  MAIN. STOPPED WHEN VOLUME IN CITY MAIN  ALLOWED FOUNSHIP FLOW. 3000 00000000000000000000000000000000
10. Describe extent of contamination and how it was cleaned up	CONKROUN EXTENT OF CONTAMINATION.  MINOR CLEMN UP WAS PERFORMED BECAUSE  THERE WAS MINOR DEBRIS NOTED AT TENE  OF INSPECTION. AREA WAS LIMED ALSO.
11. What actions will be taken to prevent a re-occurrence ? When ?	TOWNSHIP MAS AN ACTIVE ISI PROGRAM.  UNKNOWN WHAT CITY WELL DO TO CONTROL  FLOW SURGES IN THETH MAINS. TOWNSHED  RELENTLY SEALED HANHOLES IN THIS AREA.

## Sanitary Sewer Overflow (SSO) Report to PADEP

12. Other comments?	ON FURTHER INVESTIGATION WE DETERMINE THAT THEODOSTREAM MANIMEDS IN THE CENT OF ALLEMYSOON WERE FULL INDECATIONS THAT THEIR PIPES CAPACITY WAS OVERWHERMED, THUS
	THE PLANT AS DESTENDED.





Public Works Department 4444 Walbert Avenue Allentown, PA 18104-1699 Phone: 610-398-0407

Fax: 610-398-6898

## **Facsimile Transmission Sheet**

Date:

03/14/11

To:

Patric Musinski, DEP

Fax Number 570-830-3016

From:

Thomas R. Uff, Superintendent, Underground

**Utilities & Traffic** 

Subject:

**SSO** Report to DEP

Number of pages including this transmission sheet: 4

#### Message:

Please note that the SSOs occurred from the inlet chamber lid gasket, and at the gasket seal on manhole MH.1-A. These are located at the two points circled on the plan. We will repair these as soon as we can get equipment in to lift the structures to replace the gaskets.

Thomas R. Uff



**Public Works Department 4444 Walbert Avenue** Allentown, PA 18104-1699 Phone: 610-398-0407

610-398-6898 Fax:

# Facsimile Transmission Sheet

Date:

04/08/10

To:

Sheena Ripple, DEP

Fax Number 610-861-2072

From:

Thomas R. Uff, Superintendent, Underground

**Utilities & Traffic** 

Subject:

SSO Report to DEP

Number of pages including this transmission sheet: 4

### Message:

Please note that the SSOs occurred from the inlet chamber lid, and the outlet chamber lid. These are located at each end of the inverted siphon pipe that crosses the creek at the two points circled on the plan.

WATER QUALITY COUNTY: Lehigi

APR 0.8 2010

Thomas R. Uff

MUNIC: South Whi-FACILITY: South Whitehell General File

FILE CODE: GENERAL SEWALE

04 08 2010


# Sanitary Sewer Overflow (SSO) Report to PADEP

	, separate : NDLF
Date, Name, Phone # of p     completing this report	Date: 4/6/10 Name: 740MA5 UFF Signature: 7/14/16 Phone #: 616-348-0407
Your organization name a address ?	and SOUTH WHITEHALL TWP.  HUMH WALBERT ALE
Date found and specific locations of SSO ?	ALLENTOWN DA 18104  ation 3/39/2010 SANITARY SENDER SIPHON CHAMBER  ALLESS MANHOLES (MH 18 MHZ) ALONG MARTEN LUTHER HIM  TR. DRIVE, ALLENTOWN
4. How was SSO discovered By who ?	
5. Start and end time of SSO (actual or estimate?)	6N 3/30/2010 - AS RECEZVED THROUGH BRIAN CHAMBERLAN
6. Date, time and name of person who notified PADEP of SSO ?	
Description and actual or estimated volume of SSO	CHAMBERS UNKNOWN VOLUME
8. Where, <u>precisely</u> , did SSO go ? (land, roadway, basement, swale, storm sewer, creek, etc)	550 WAS WASHED AWAY BY CREEK FLOW
9. What caused SSO ? How was it stopped ?	I O I POSTIBLE CAUSE OF WHICH OVERWHEND (ITY SYSTEM AND BACKED UP INTO TOWNSHIP MAIN. STORPED WHEN VOLUME IN CITY MAIN ALLOWED TOWNSHIP FLOW
10. Describe extent of contamination and how it was cleaned up	WINDROWN EXTENT OF CONTAMENATION.  MINOR CLEAN UP WAS PERFORMED BELAUSE  THERE WAS PERFORMED BE TIED  OF INSPECTION.
What actions will be taken to prevent a re-occurrence?     When ?	TOLOWSHIP HAS AN ACTIVE ISI PROGRAM.  UNKNOWN WHAT CITY WILL DO TO CONTROL  FLOW SURGES IN THEER MAINS.

3 /4

## Sanitary Sewer Overflow (SSO) Report to PADEP 04 08 2010

	00		 	
12. Other comments ?			. pří	
		()	 	





October 20, 2010

CERTIFIED MAIL NO.: 7010 0290 0000 2762 7300

South Whitehall Township 4444 Walbert Avenue Allentown, PA 18104-1699

Attention: Mr. John Hammer

Township Manager

Re: Sewage

South Whitehall Township, Lehigh County

Dear Mr. Hammer:

This letter is intended as a reminder of South Whitehall Township's responsibility to notify the Department of any sanitary sewer overflows (SSO) which occur within your collection system.

On September 30 and October 1, 2010, the region experienced excessive rainfall. As a result, several municipalities in the Lehigh Valley reported SSOs from their systems. The Department has received similar SSO notifications in the past, most recently March 30, 2010 from South Whitehall Township. At that time, other municipalities in proximity to South Whitehall Township experienced similar SSOs. These municipalities experienced similar SSOs during the storm of September 30 and October 1, 2010 and notified the Department as such.

To date, the Department has not received any notification from South Whitehall Township regarding any SSOs as a result of the storm of September 30 and October 1, 2010. If such SSOs occurred, the Department requests that South Whitehall Township submit a written notification within 5 days of receipt of this letter. Please use the format followed when the March 30, 2010 notification was submitted.

If you have any questions concerning this correspondence, you may contact me at 570-826-2326.

Sincerely,

Patrick Musinski

Water Quality Specialist Supervisor

Water Management Program